

PLATOS MAGNÉTICOS CIRCULARES

Código	Dimensiones	Agujero centrador Ø max. (mm)	Profundidad máxima (mm)	Vida útil (mm)	Max. RPM	Dimensión X (mm)
13.10.001	Ø100 FP	12	5	5	1500	16,0
13.10.002	Ø130 FP	12	5	5	1200	17,5
13.10.003	Ø160 FP	15	5	7	1000	22,5
13.10.004	Ø200 FP	15	5	5	800	31,5
13.10.006	Ø250 FP	25	22	5	700	40,0
13.20.004	Ø200 MX	10	5	5	800	26,0
13.20.006	Ø250 MX	25	22	5	700	31,5
13.20.007	Ø300 MX	20	22	5	700	37,0
13.20.008	Ø350 MX	25	22	7	600	36,0
13.20.009	Ø400 MX	30	22	7	500	48,0
13.20.010	Ø450 MX	30	25	8	450	47,0
13.20.011	Ø500 MX	20	25	8	400	46,0

Nota: taladrar sólo en las tiras de hierro.
Para otras acciones, por favor consulte.

